GL4736

39 repair / maintenance records | Total cost: $41,343.35

Repair & maintenance

Date	Category / procedure	Description	Cost
Oct 06, 2026	Roadcall / Jump start	GL4736/T0940 (Marcus Rashad Newton) Zeegot $150 truck jump start, Auto Health / Gill Express Fresno CA inv 28368 10/06, labor only. EFS 3191786151 ref 165787487 (no tag - per last WO #SR)	$150.00
Sep 16, 2026	Repair / TRK Complex Repair		$1,590.00
Sep 03, 2026	Repair / TRK Drive Tire replacement	Drive tire replacement RRO position. 295/75R22.5 RDR52 LRH. Puncture too large to repair. Love's Baxter TN,	$560.87
Aug 26, 2026	Repair / TRK Complex Repair		$4,284.93
Aug 13, 2026	Repair / TRK Air System Leakage	Notes 4736 Azamat air leak.	$211.68
Aug 12, 2026	Repair / TRK Complex Repair	GL4736 Kholmirzaev Azamat Zeegot PO Pm service TRK complex repair	$3,485.97
Apr 08, 2026	Repair / TRK Coolant Leakage	4736 Veysel trans cooler	$1,627.55
Apr 07, 2026	Repair / TRK Radiator	4736 Veysel radiator insallation	$1,375.00
Apr 05, 2026	Roadcall / TRK coolant leakage	4736 Veysel road service	$100.00
Apr 03, 2026	Repair / TRK Lights repair	4736 Veysel service	$505.00
Mar 19, 2026	Repair / TRK Steer Tire Replacement	4736 Cihan steer tires	$1,035.84
Mar 12, 2026	Maintenance / PM Service	4736 Cihan PM	$536.38
Mar 12, 2026	Maintenance / PM Service	4757 Azimjon PM and tires	$1,327.18
Jan 15, 2026	Maintenance / PM Service	4736 pm service paid with card	$550.34
Dec 16, 2025	Repair / TRK Battery replacement	GL4736 Cihan Yildirim Batteries	$1,138.82
Nov 04, 2025	Repair / TRK Complex Repair	4736 Cihan/Ali Firat FIdan ABS and other repairs	$720.00
Oct 28, 2025	Repair / TRK Windshield	4736 Cihan windshield	$323.84

Date	Category / procedure	Description	Cost
Oct 05, 2025	Repair / TRK Coolant Leakage	4736 Cihan water pump	$1,141.19
Sep 23, 2025	Maintenance / DOT (Annual Inspection)	4736 Cihan dot.	$60.00
Sep 18, 2025	Roadcall / TRK starter failure	4736 Cihan road service	$875.00
Sep 12, 2025	Maintenance / PM Service	4736 Cihan PM	$504.55
Jul 07, 2025	Repair / TRK Complex Repair	GL4736 complex repair PM	$5,909.62
May 15, 2025	Repair / TRK ABS failure	GL4736 ABS failure paid by wire	$388.15
May 08, 2025	Repair / TRK Air System Leakage	3in1 air line replacement	$250.00
Mar 01, 2025	Repair / TRK Steer Tire Replacement	GL4736 TRK Steer tires / Replacement	$1,569.76
Mar 01, 2025	Maintenance / old - PM (Preventative Maintenance)	GL4736 Manuchar Gogilava PM	$579.13
Feb 19, 2025	Other / Old-TRK Steer tires / Replacement	GL4736 Steer tires replacement	$2,260.14
Feb 15, 2025	Repair / TRK Windshield	GL4736 TRK Windshield	$275.00
Dec 10, 2024	Repair / TRK Oil Leakage		$1,704.03
Dec 06, 2024	Repair / TRK Oil Leakage		$1,479.55
Dec 04, 2024	Repair / TRK Hub Repair / Replacement		$465.45
Nov 21, 2024	Repair / TRK Oil Leakage		$1,032.66
Nov 19, 2024	Repair / TRK Other Repair		$142.29
Nov 09, 2024	Repair / TRK Alignment/Balancing		$221.59
Sep 17, 2024	Repair / TRK Hub Repair / Replacement		$776.35
Sep 17, 2024	Repair / Not set		$122.00

Date	Category / procedure	Description	Cost
Jul 31, 2024	Repair / Old-TRK Tire Repair / Replacement		$94.01
Apr 04, 2024	Diagnostics / Other diagnostics	4736 Veysel diagnostics	$157.28
Jul 18, 2025, 14:24	Repair / TRK Coolant Leakage	GL4736 - Cihan Yildirim radiator	$1,812.20

Unclassified records - requires review

Date	Category / procedure	Description	Cost
Apr 06, 2026	Parts / Overall parts	GL4736 - Veysel Bulgaz radiator	$1,949.48
Apr 11, 2024	Unclassified / Not set		$2,238.04
Apr 02, 2024	Unclassified / Not set		$3,353.52
Feb 27, 2024	Unclassified / Not set		$627.50
Feb 07, 2024	Unclassified / Not set		$116.34
Feb 07, 2024	Unclassified / Not set		$139.30
Dec 07, 2023	Unclassified / Not set		$201.91
Nov 24, 2023	Unclassified / Not set		$516.32
Nov 03, 2023	Unclassified / Not set		$250.00
Nov 03, 2023	Unclassified / Not set		$250.00
Oct 31, 2023	Unclassified / Not set		$1,854.52

Source: DataTruck non-archived records, exported October 11, 2026. Dates: scheduled dates. Costs: Total pay. Vendor, location and mileage are available only when recorded in Notes. Invoice attachments were not individually checked. Unclassified records require review.