GL6877

39 repair / maintenance records | Total cost: $35,176.59

Repair & maintenance

Date	Category / procedure	Description	Cost
Oct 06, 2026	Roadcall / TRK TOW	GL6877/T0949 (Erfanullah Omaid) Zeegot $1552.50 HD wrecker truck+trailer tow I-20 exit 367 Mingus TX -> 6808 FM 113 Cool TX, Freddy's Auto Parts Ranger TX inv 47581, created 10/05: tow 1500 + processing fee 52.50. 686156 mi. CC 1781 #Sam	$1,552.50
Oct 05, 2026	Diagnostics / Other diagnostics	GL6877 (Erfanullah Omaid) Zeegot $345 road service #2 (engine oil leak saga, see /11465) - Fowler's Diesel Services LLC (318-529-2691) INV 004606, 10/05. Work details not provided, only vendor email. EFS 2702867062 ref 165771900 #Sam	$345.00
Oct 04, 2026	Diagnostics / Other diagnostics	GL6877 (Erfanullah Omaid) Zeegot $773.76 road call Monahans TX I-20, oil tank empty/no oil psi - added 4gal Rotella, cleared codes, psi 52; small engine leak NOT found, needs pressure wash - Big Country Pecos TX INV W03187, 10/04. CC 1781 #ryan	$773.76
Sep 08, 2026	Roadcall / TRK radiator	Unit GL6877 / Omaid Erfanullah / Zeegot / $491.18 / Blown drive tire - Sailun S768 CSDRIVE / Rice Tire Hagerstown MD / EFS 1225208416 / #james	$491.18
Aug 25, 2026	Repair / TRL Tire Repair		$465.50
Aug 17, 2026	Repair / TRK Lights repair	Notes 6877 Omaid headlight changed.	$170.35
Aug 14, 2026	Repair / TRK Lights repair	Notes 6877 Omaid headlight part.	$392.68
Aug 13, 2026	Maintenance / PM Service	GL6877 Omaid Erfanullah Zeegot PM service	$450.00
Aug 06, 2026	Repair / TRK Complex Repair	GL6877 Omaid Erfanullah Zeegot Pm service 3in1 cable Engine valve adjust Oil pan Air dryer All injecters Air isolator cleaner Steer tire 2x $4,620.24	$4,620.24
Jul 16, 2026	Maintenance / DOT (Annual Inspection)	DOT inspection	$65.09
Apr 27, 2026	Repair / TRK TIre Rim Replacement	6877 John Zeegot 2 Tires paid by card 0937 Goodyear tire	$805.67
Apr 24, 2026	Diagnostics / Programming	6877 Check light and reprogramming	$52.07
Mar 23, 2026	Repair / TRK Complex Repair	6877 John filter injectors.	$733.00
Mar 05, 2026	Roadcall / TRK winch out	GL6877 - John Diaz winch out	$1,196.25
Feb 01, 2026	Maintenance / PM Service	6877 farhad ali PM.	$546.97

Date	Category / procedure	Description	Cost
Dec 02, 2025	Repair / TRK TIre Rim Replacement	6877 Bilal tire patch	$62.76
Nov 29, 2025	Repair / TRK Complex Repair	6877 Bilal str tire washer pmp.	$1,198.69
Oct 28, 2025	Maintenance / PM Service	6877 Bilal PM	$546.47
Oct 22, 2025	Repair / TRK Steer Tire Replacement	6877 Bilal Steer tires	$1,651.03
Sep 15, 2025	Repair / TRK Brake Issue	6877 Bilal brakes.	$583.67
Sep 08, 2025	Repair / TRK ABS failure	6877 Bilal ABS 1613.53 was paid with CC rest with EFS	$1,836.75
Aug 02, 2025	Repair / TRK Oil Leakage	6877 Ziad Bellid oil pan replacement 2 Part of the payment	$1,846.32
Jun 29, 2025	Repair / TRK Drive Tire Repair	6877 Ziad drive tire.	$361.13
Jun 24, 2025	Repair / TRK Complex Repair	6877 Ziad bumper tires alignment hub seal	$3,105.15
Jun 02, 2025	Other / Old-Jump start		$263.75
Apr 17, 2025	Repair / TRK Electrical Issues		$600.00
Apr 11, 2025	Repair / TRK Complex Repair		$2,204.41
Apr 02, 2025	Repair / TRK Other Repair	unit unknown	$2,199.36
Mar 20, 2025	Diagnostics / Other diagnostics	GL6877 Ekhrom Aliev Truck diagnostics	$254.53
Mar 04, 2025	Repair / Old-TRK TOW	GL6877 Abdul Qader Khodadadi TRK TOW	$1,300.00
Feb 14, 2025	Other / Old-locksmith	GL6877 locksmith	$275.00
Jan 24, 2025	Repair / Old-TRK Lights repair		$90.39
Dec 23, 2024	Maintenance / old - PM (Preventative Maintenance)		$1,247.42
Aug 30, 2024	Repair / Not set		$65.28
Aug 28, 2024	Repair / Not set		$1,310.63

Date	Category / procedure	Description	Cost
Aug 25, 2024	Repair / TRK Wiper blades replacement		$11.77
Jul 01, 2024	Repair / Not set	6877 oraz tire change road call	$463.50
Jun 29, 2024	Repair / Not set	6877 orazmuhammad fuel	$700.00
Jun 27, 2024	Repair / Not set		$338.32

Unclassified records - requires review

Date	Category / procedure	Description	Cost
Oct 05, 2026	Parts / Overall parts	GL6877 (Erfanullah Omaid) Zeegot $70.10 reserve engine oil 2 gal Delo 400 SynBlend 10W30 @32.99 + tax 4.12 - engine oil leak, see - Pilot #1205 Monahans TX tran 6619791, 10/05. EFS 2940686670 ref 165754394. Tony	$70.10
Jan 16, 2026	Under Account / Excel parts	6877 Fuel Filter hub cap	$58.74
Jan 16, 2026	Under Account / Excel parts	6877 rotors	$291.00
Sep 04, 2025	Parts / Overall parts	6877 yard washer and bolt kits	$22.74
Sep 04, 2025	Parts / Overall parts	6877 yard parts	$272.95
Jul 31, 2025	Parts / Overall parts	6877 Ziad oil pan payment for parts amount $900	$900.00
Jul 04, 2024	Other / Not set	Oraz Fuel	$600.00
Apr 02, 2024	Unclassified / Not set		$1,361.42
Mar 29, 2024	Unclassified / Not set		$1,600.00
Feb 21, 2024	Unclassified / Not set		$49.99
Feb 03, 2024	Unclassified / Not set		$100.00
Jan 31, 2024	Unclassified / Not set		$430.00
Jan 30, 2024	Unclassified / Not set		$150.00
Jan 27, 2024	Unclassified / Not set		$1,141.67

Date	Category / procedure	Description	Cost
Nov 17, 2023	Unclassified / Not set		$613.40
Oct 31, 2023	Unclassified / Not set		$783.21
Oct 30, 2023	Other / Not set		$783.21
-	Unclassified / Not set		$593.99

Source: DataTruck non-archived records, exported October 11, 2026. Dates: scheduled dates. Costs: Total pay. Vendor, location and mileage are available only when recorded in Notes. Invoice attachments were not individually checked. Unclassified records require review.