GL6879

37 repair / maintenance records | Total cost: $43,228.44

Repair & maintenance

Date	Category / procedure	Description	Cost
Jul 16, 2026	Repair / TRK ABS failure	GL6879 yard ABS sensr	$817.69
Jun 02, 2026	Repair / TRK Steer Tire Replacement	8 drives 2 steers for the unit 6879	$3,273.59
Feb 24, 2026	Accident / TRK Accident Damage	GL6879 - Muhammet Ermis	$3,438.68
Feb 11, 2026	Repair / TRK Complex Repair	gl6879 Muhammet Ermis fuel injector seal, fuel injector lines, diagnostics	$2,557.13
Feb 05, 2026	Maintenance / PM Service	6879 Ermis PM.	$546.97
Jan 26, 2026	Roadcall / TRK winch out	6879 Ermis winch out.	$672.00
Jan 02, 2026	Repair / TRK TIre Rim Replacement	6879 Muhammet tire.	$280.79
Dec 09, 2025	Repair / TRK Complex Repair	6879 Ermis air compressor	$2,232.66
Dec 08, 2025	Repair / TRK Battery replacement	6879 Ermis battery air dryer	$1,907.35
Dec 07, 2025	Diagnostics / Other diagnostics	6879 Ermis RS diagnostics.	$314.18
Oct 30, 2025	Repair / TRK Body repair	6879 Ermis hood mirror. $562.49 Yigit charge	$648.18
Oct 22, 2025	Repair / TRK Steer Tire Replacement	6879 Muhammet tires.	$1,725.09
Oct 21, 2025	Repair / TRK Brake Issue	6879 Ermis brakes. paid with 2 codes	$4,663.95
Oct 18, 2025	Roadcall / TRK Air Leak	6879 Muhammet road call	$202.00
Sep 08, 2025	Maintenance / PM Service	GL6879 - Muhammet Ermis Pm Service	$438.48
Jul 26, 2025	Repair / TRK TIre Rim Replacement	6879 Muhammet steer axle left rim	$459.94

Date	Category / procedure	Description	Cost
Jul 26, 2025	Repair / TRK Brake Issue	6879 Muhammet tire check	$130.63
Jul 25, 2025	Repair / TRK Complex Repair	6879 Ermis brakes T8010 3 tires / brake chamber	$2,784.09
Jul 23, 2025	Diagnostics / TRK tire inspection	6879 Ermis steer tire check.	$80.07
Jul 17, 2025	Repair / TRK Drive Tire Repair	6879 Ermis tire patch	$64.13
Jun 20, 2025	Maintenance / PM Service	6879 Muhammet PM	$525.51
Jun 11, 2025	Other / Old-Nox sensor	GL6879 Nox sensor	$1,942.14
May 06, 2025	Repair / Old-TRK Suspension issue	6879 Air bag set power steering pump	$1,895.09
Feb 18, 2025	Repair / TRK Brake Issue	GL6879 TRK Brake Issue	$515.67
Feb 18, 2025	Maintenance / DOT (Annual Inspection)	GL6879 Annual Inspection	$95.00
Feb 14, 2025	Repair / TRK Electrical Issues	GL6879 Nox sensor	$1,486.34
Jan 03, 2025	Repair / TRK Alignment/Balancing		$142.17
Dec 17, 2024	Repair / TRK Other Repair	load id 2055000 Aleksandar Bozhinov	$430.00
Dec 16, 2024	Repair / TRK Other Repair	Aleksandar Bozhinov	$27.43
Dec 16, 2024	Repair / Old-TRK Tire Repair / Replacement	Aleksandar Bozhinov	$2,276.37
Dec 03, 2024	Repair / TRK Other Repair		$2,916.86
Nov 27, 2024	Accident / TRK Accident Damage		$1,611.10
Nov 07, 2024	Repair / Not set		$225.00
Sep 16, 2024	Repair / Not set		$192.70
May 28, 2024	Repair / Not set		$108.50
May 28, 2024	Repair / Not set		$1,363.73

Date	Category / procedure	Description	Cost
Aug 26, 2025, 10:15	Repair / TRK Drive Tire replacement	GL6879 - Muhammet Ermis truck drive tire	$237.23

Unclassified records - requires review

Date	Category / procedure	Description	Cost
Jul 07, 2024	Other / Not set	truck wash	$140.20
May 13, 2024	Unclassified / Not set		$1,092.88
Apr 02, 2024	Unclassified / Not set		$435.00
Mar 24, 2024	Unclassified / Not set		$3,499.85
Feb 15, 2024	Unclassified / Not set		$49.99
Feb 08, 2024	Unclassified / Not set		$68.72
Jan 19, 2024	Unclassified / Not set		$545.46
Jan 03, 2024	Unclassified / Not set		$971.25
Sep 30, 2023	Other / Not set		$867.78

Source: DataTruck non-archived records, exported October 11, 2026. Dates: scheduled dates. Costs: Total pay. Vendor, location and mileage are available only when recorded in Notes. Invoice attachments were not individually checked. Unclassified records require review.