GL4728

55 repair / maintenance records | Total cost: $46,827.02

Repair & maintenance

Date	Category / procedure	Description	Cost
Oct 07, 2026	Repair / TRK Brake Issue	GL4728 Yusuf Ismail White Way TA Lake Township OH -243358 10/07: brake light on, replaced brake pressure switch + harness. Sensor 45.97, harness 66.92, parts run 65.35, shop 24.74, labor 1.5h 214.49, tax 28.18. EFS ref 165816093 #Sam	$445.65
Sep 22, 2026	Repair / TRK Complex Repair		$1,033.04
Sep 17, 2026	Repair / TRK Complex Repair	GL4728 (VIN UF4728) White Way $693.00 forced regen - Southern Diesel Repair Dallas (Greenville TX), INV-393, SO-1498, 09/17: diag HC doser codes, cleaned 7th injector, forced regen. 467220 mi. EFS ref 165441850. #SR	$693.00
Sep 16, 2026	Repair / TRK Differential repair/replacement	WIRE payment $9,298.78 | front rear end changed | GL4728 Michael Johnson | vendor unknown - receipt pending	$9,298.78
Sep 11, 2026	Roadcall / TRK TOW	GL4728 (trailer T0937) Michael Johnson Zeegot $931.50 towing heavy duty tow differential issue Caddo Mills TX to shop Dallas TX trailer moved to parking | Caddo Mills, TX	$931.50
Sep 09, 2026	Diagnostics / TRK Forced Regen	Michael Johnson manual regen not allowed we did regen	$113.23
Aug 31, 2026	Diagnostics / Programming	GL4728 / Michael / Zeegot / $129.60 / Computer Diagnostics Service / EZ Truck Repair INV-9760 / #sam	$129.60
Aug 03, 2026	Maintenance / PM Service	GL4728 Michael Johnson Zeegot PO PM service AC Air leakage 5th wheel repair Power steering filter	$1,041.00
Jul 21, 2026	Roadcall / Jump start	Notes 4728 Michael jumpstart.	$215.00
Jul 09, 2026	Repair / TRL Tire replacement	Notes 4728 Roadservice tire Roadservice changed 2 trailer tires, rims, mudflap, brackets, valve	$1,881.31
Jun 30, 2026	Repair / TRK Steer Tire Replacement	GL4728 Steer tires 6 drive tires Brakes	$3,959.00
Jun 21, 2026	Repair / TRK Drive Tire Repair	Notes 4728 Michael tire patch.	$71.53
Jun 11, 2026	Roadcall / Jump start	Notes 4728 Michael jump start.	$350.00
May 19, 2026	Repair / TRK Drive Tire replacement	4728 Michael drive tire.	$628.82
Mar 27, 2026	Repair / TRK Drive Tire Repair	4728 Michael tire patch	$95.00

Date	Category / procedure	Description	Cost
Mar 23, 2026	Repair / TRK Starter failure	GL4728 - Michael Johnson Starter	$637.41
Mar 23, 2026	Repair / TRK Starter failure	4728 Michael road service 250 driver charge	$535.00
Mar 21, 2026	Repair / Inverter Installation/Repair	4728 Michel inverter ins	$239.69
Mar 21, 2026	Repair / Inverter Installation/Repair	4728 Michael new invertor.	$426.99
Mar 13, 2026	Maintenance / PM Service	4728 Michael PM.	$416.12
Mar 11, 2026	Repair / TRK Drive Tire Repair	4728 Michael tire patch	$82.60
Mar 02, 2026	Repair / TRK Drive Tire Repair	4728 Michael tire patch.	$185.00
Sep 26, 2025	Roadcall / Jump start	GL4728 - Feilbach Zachary	$1,674.13
Sep 23, 2025	Roadcall / Jump start	4728 Feilbach jump start	$375.76
Sep 19, 2025	Maintenance / PM Service	GL - 4728 Felibach Zachary PM service	$987.33
Sep 04, 2025	Repair / TRK Coolant Leakage	4728 Nalan coolant leak	$432.81
Aug 18, 2025	Repair / TRK Horn repair	4728 Nalan city horn.	$192.04
Aug 01, 2025	Roadcall / Engine belt repair	GL4728 - Nalan Urel road service	$459.28
Jul 10, 2025	Repair / TRK Coolant Leakage	4728 Nalan coolant	$731.07
Jun 18, 2025	Parts / old-Specific Parts	4728 Nalan Fuel caps.	$136.93
Jun 14, 2025	Repair / TRK Drive Tire Repair	4728 Azimjon tire change.	$503.19
Jun 07, 2025	Maintenance / PM Service		$607.32
May 31, 2025	Repair / Old-TRK Suspension issue	GL4728 Azimjon Gayratov King pins	$4,532.00
May 28, 2025	Repair / TRK Oil Leakage	Complex repair (Oil leakage from differential / Oil pan)	$3,090.00
May 27, 2025	Repair / TRK Drive Tire Repair	GL4728 Azimjon Gayratov Tire patch	$53.31

Date	Category / procedure	Description	Cost
May 15, 2025	Repair / TRK Alignment/Balancing	GL4728 Azimjon Gayratov 2 axle ALIGNMENT	$231.00
May 11, 2025	Repair / TRK Steer Tire Replacement	GL4728 Azimjon Gayratov Steer Tire Replacement	$1,891.04
Apr 28, 2025	Repair / TRK Complex Repair		$162.75
Apr 22, 2025	Repair / TRK Drive Tire Repair		$635.00
Apr 04, 2025	Repair / Old-TRK Lights repair	GL4728 Azimjon Gayratov Tail light	$45.24
Mar 30, 2025	Repair / TRK Drive Tire Repair		$240.00
Mar 29, 2025	Parts / old-General Parts		$97.86
Mar 24, 2025	Repair / TRK Alignment/Balancing	GL4728 Azimjon Gairatov Tire change	$430.00
Mar 09, 2025	Maintenance / old - PM (Preventative Maintenance)	GL4728 Azimjon Gayratov PM	$485.38
Dec 28, 2024	Repair / Old-TRK Lights repair		$70.70
Dec 22, 2024	Maintenance / old - PM (Preventative Maintenance)		$702.85
Nov 23, 2024	Repair / TRK Alignment/Balancing		$871.20
Nov 08, 2024	Repair / TRK Other Repair		$260.10
Sep 02, 2024	Repair / Not set		$24.07
Aug 30, 2024	Repair / TRK Brake Issue		$1,264.53
Jul 27, 2024	Repair / Not set		$951.28
Jul 25, 2024	Repair / Old-TRK Tire Repair / Replacement		$0.00
Jul 03, 2024	Maintenance / old - PM (Preventative Maintenance)		$480.83

Date	Category / procedure	Description	Cost
Jul 01, 2024	Repair / Not set	Load ID: 0271637 timofti lumper	$323.75
Jun 29, 2024	Repair / Not set		$475.00

Unclassified records - requires review

Date	Category / procedure	Description	Cost
Sep 23, 2026	Parts / Overall parts	GL4728 Yusuf Ismail Zeegot $129.65 Pilot - parts. NEW DRIVER DID NOT PROVIDE RECEIPT despite being informed. Booked per Sean without receipt	$129.65
Mar 05, 2026	Parts / Overall parts	4728 Michael wiper	$21.40
Jun 19, 2025	Parts / old-Equipment	4728 Nalan parts	$29.21
Mar 27, 2024	Other / Not set		$1,739.46
Jan 04, 2024	Unclassified / Not set		$672.00
Dec 31, 2023	Unclassified / Not set		$519.30
Dec 11, 2023	Unclassified / Not set		$157.60
Nov 29, 2023	Unclassified / Not set		$75.00
Nov 22, 2023	Unclassified / Not set		$29.55
Nov 22, 2023	Unclassified / Not set		$21.59
Nov 17, 2023	Unclassified / Not set		$19.86
Oct 01, 2023	Unclassified / Not set		$800.15
Oct 01, 2023	Unclassified / Not set		$47.44
Oct 01, 2023	Unclassified / Not set		$800.15

Source: DataTruck non-archived records, exported October 11, 2026. Dates: scheduled dates. Costs: Total pay. Vendor, location and mileage are available only when recorded in Notes. Invoice attachments were not individually checked. Unclassified records require review.