GL5333

39 repair / maintenance records | Total cost: $26,814.39

Repair & maintenance

Date	Category / procedure	Description	Cost
Oct 07, 2026	Roadcall / Jump start	GL5333/T3202 (Bertholand Louis Jeune) Zeegot $156 jump start, C&P Towing & Transport Pompano Beach FL Towbook inv 10101, RoadSync 10017585, 10/07: 150 + conv fee 6. EFS 1013767698 ref 165807179 #SR	$156.00
Sep 21, 2026	Repair / TRK Electrical Issues	GL5333 Bertholand Louis Jeune Zeegot $442.69 TA Paulsboro NJ -006347: right tail light broken - new tail light + wiring harness installed, working properly | Paulsboro, NJ	$442.69
Sep 11, 2026	Repair / TRK Drive Tire Repair	GL5333 Bertholand Louis Jeune Zeegot $78.65 drive tire patch bolt in LFI drive tire plug patch Napoleon OH | Napoleon, OH	$78.65
Sep 01, 2026	Repair / TRK Complex Repair		$2,759.00
Aug 18, 2026	Roadcall / Jump start	Unit GL5333 / Bertholand Louis Jeune / Zeegot / $221.92 / jumpstart / #ryan	$221.92
Aug 03, 2026	Repair / TRK Mud Flap repair	Notes 5333 Bertholand mudflap.	$86.31
Jul 10, 2026	Roadcall / Jump start	Notes GL5333 Louis jumpstart.	$315.65
Jun 24, 2026	Repair / TRK Complex Repair	GL5333 Pm service Brakes DOT Lights Steer tire balance Air drye	$2,522.94
Apr 13, 2026	Repair / TRK Drive Tire Repair	Truck drive tire patched	$68.19
Apr 01, 2026	Maintenance / PM Service	GL5333 - Aydarsho Merovarsho PM coolant sensor	$737.26
Feb 27, 2026	Roadcall / Jump start	5333 Abdulsamet jumpstart.	$400.95
Jan 23, 2026	Roadcall / TRK TOW	GL5333 - Abdulsamet Sayhan - Zeegot	$1,251.90
Jan 20, 2026	Maintenance / PM Service	5333 Abdulsamet PM.	$546.47
Jan 16, 2026	Maintenance / DOT (Annual Inspection)	5333 Abdulsamet DOT.	$92.66
Jan 12, 2026	Repair / TRK TIre Rim Replacement	GL5333 truck tires repalcement	$972.85
Sep 04, 2025	Maintenance / PM Service	5333 yasin pm mudflaps	$845.04

Date	Category / procedure	Description	Cost
Aug 24, 2025	Repair / TRK Drive Tire replacement	GL5333 Yasin drive tires	$1,100.00
Aug 11, 2025	Repair / TRK Steer Tire Replacement	5333 Yasin Karsit Two steer tires	$1,786.77
Jul 27, 2025	Repair / TRK Drive Tire replacement	5333 Omer Drive tire	$1,037.46
Jun 27, 2025	Maintenance / PM Service	5333 Omer PM	$531.90
May 22, 2025	Repair / TRL Oil Leakage	5333 Hamidullah Oil pan	$3,738.14
Apr 28, 2025	Repair / Old-TRK TOW		$1,500.00
Mar 10, 2025	Maintenance / old - PM (Preventative Maintenance)	GL5333 Hamidullah Umar Khan PM	$267.52
Feb 23, 2025	Maintenance / old - PM (Preventative Maintenance)	5333 Hamidulah PM service	$682.62
Feb 23, 2025	Parts / old-Specific Parts	5333 Hamidulah equipment	$26.49
Feb 20, 2025	Other / Old-TRK Drive tires / Replacement	GL5333 Hamidullah Umar Khan Tire patch	$58.00
Feb 16, 2025	Parts / old-Specific Parts	GL5333 Equipment	$9.37
Jan 10, 2025	Parts / old-Specific Parts		$52.68
Jan 10, 2025	Other / Old-TRK Mud Flap repair		$96.97
Jan 06, 2025	Repair / TRK ABS failure		$203.17
Dec 09, 2024	Repair / TRK Other Repair		$95.00
Nov 23, 2024	Repair / Old-TRK Tire Repair / Replacement		$1,010.37
Sep 18, 2024	Repair / Not set		$350.00
Sep 18, 2024	Repair / Not set		$63.60

Date	Category / procedure	Description	Cost
Aug 24, 2024	Repair / Old-TRK Tire Repair / Replacement		$1,334.49
Jun 10, 2024	Repair / Not set		$47.95
Jun 02, 2024	Repair / TRK Other Repair		$524.88
May 31, 2024	Maintenance / old - PM (Preventative Maintenance)		$518.53
Jun 09, 2020	Repair / TRK Windshield	5333 Aydarsho Meravarsho	$280.00

Unclassified records - requires review

Date	Category / procedure	Description	Cost
Apr 29, 2024	Unclassified / Not set		$713.12
Feb 29, 2024	Unclassified / Not set		$546.52
Feb 28, 2024	Unclassified / Not set		$9,453.98
-	Unclassified / Not set		$72.02

Source: DataTruck non-archived records, exported October 11, 2026. Dates: scheduled dates. Costs: Total pay. Vendor, location and mileage are available only when recorded in Notes. Invoice attachments were not individually checked. Unclassified records require review.