GL2577

42 repair / maintenance records | Total cost: $46,678.36

Repair & maintenance

Date	Category / procedure	Description	Cost
Aug 19, 2026	Repair / TRK Complex Repair		$4,206.12
Jul 06, 2026	Repair / TRK Drive Tire replacement	Blown out truck drive tire, forced to drive till shop to avoid road service Blown tire replaced	$447.29
Jul 02, 2026	Repair / TRK AC system repair	GL2577 AC dryer AC vaccumoe Check blower	$348.00
Jul 02, 2026	Repair / TRK AC system repair	Notes 2577 Osman AC fixed.	$711.39
Jun 11, 2026	Maintenance / PM Service	PM service Front rotors brake shoes hub seals 3in1 airline replace APU betteries	$4,465.18
May 18, 2026	Repair / TRK Brake Issue	2577 Osman brakes.	$1,606.71
May 11, 2026	Repair / TRK Complex Repair	2577 osman compressor.	$393.74
Apr 05, 2026	Maintenance / PM Service	2577 Osman PM	$869.67
Apr 03, 2026	Repair / TRK Drive Tire replacement	2577 osman tire change	$651.07
Feb 09, 2026	Repair / TRK Drive Tire Repair	2577 Osman TR tire patch	$75.48
Jan 29, 2026	Roadcall / TRK starter failure	2577 Osman Roadside service.	$465.00
Jan 23, 2026	Repair / TRK Steer Tire Replacement	GL2577 Osman 2 steer tires, shock absorbers	$2,296.95
Jan 17, 2026	Maintenance / PM Service	2577 osman PM service	$571.85
Jan 11, 2026	Repair / TRK Starter failure	GL2577 TRK Starter failure	$800.63
Jan 11, 2026	Repair / TRK Starter failure	GL2577 Osman Abdenabi New Starter + replacement	$522.30
Jan 07, 2026	Repair / TRK Battery replacement	2577 Osman batteries paid by card	$3,631.14
Dec 30, 2025	Roadcall / TRK TOW	2577 Osman towing	$800.00

Date	Category / procedure	Description	Cost
Dec 29, 2025	Repair / TRK Starter failure	2577 Osman jumpstart.	$145.37
Dec 12, 2025	Maintenance / DOT (Annual Inspection)	2577 T8457 Osman DOT.	$150.06
Sep 12, 2025	Maintenance / PM Service	2577 Aqil pm.	$561.96
Aug 28, 2025	Repair / TRK Steer Tire Replacement	2577 Aqil steer tires	$1,024.07
Jul 30, 2025	Roadcall / TRK radiator	2577 Aqil repair paid with 2 moneycodes	$2,156.00
Jul 30, 2025	Diagnostics / TRK Brake Inspection	2577 Aqil truck brakes	$78.01
Jul 29, 2025	Repair / TRK Radiator	GL2577 - Aqil Malayar radiator replaced	$3,505.81
Jul 14, 2025	Maintenance / PM Service	GL2577 PM service	$863.67
Jun 29, 2025	Repair / TRK Drive Tire Repair	2577 Mohammad tire.	$1,331.44
Jun 19, 2025	Repair / TRK Coolant Leakage	GL2577 - Mohammad Raouf Abasin coolant sensor	$2,759.95
Jun 12, 2025	Repair / TRK Drive Tire Repair	2577 Mohammad tire change.	$384.20
May 09, 2025	Repair / TRK Drive Tire Repair	2577 Abasin 2 drive tires	$783.17
May 06, 2025	Other / Old-TRK Transmission related issue	GL2577 - TRK Transmission related issue	$75.00
Apr 18, 2025	Repair / TRK Def system issue	GL2577 Green Way Def system issue	$1,481.21
Mar 29, 2025	Repair / Old-TRK TOW		$450.00
Mar 29, 2025	Repair / TRK Drive Tire Repair		$74.45
Mar 14, 2025	Repair / Old-TRK Air conditioner service	GL2577 Keosha Maxey TRK Air conditioner service	$356.38
Mar 08, 2025	Repair / TRK Coolant Leakage	GL2577 Keosha Maxey TRK Coolant Leakage	$2,500.00
Mar 07, 2025	Diagnostics / Other diagnostics	GL2577 Keosha Maxey diagnostics	$250.00
Dec 30, 2024	Repair / TRK Oil Leakage		$585.14

Date	Category / procedure	Description	Cost
Dec 09, 2024	Maintenance / PM Service		$493.35
Sep 05, 2024	Repair / TRK Hub Repair / Replacement		$1,411.33
Jul 25, 2024	Repair / Old-TRK Tire Repair / Replacement		$557.06
Jul 17, 2024	Repair / Not set		$1,838.21
-	Repair / TRK Other Repair	Waiting for an invoice.	$0.00

Unclassified records - requires review

Date	Category / procedure	Description	Cost
Apr 26, 2024	Unclassified / Not set		$2,128.86
Apr 15, 2024	Unclassified / Not set		$401.00
Apr 06, 2024	Unclassified / Not set		$60.00
Feb 19, 2024	Other / Not set		$522.46
Nov 30, 2023	Unclassified / Not set		$49.99
-	Unclassified / Not set		$663.46

Source: DataTruck non-archived records, exported October 11, 2026. Dates: scheduled dates. Costs: Total pay. Vendor, location and mileage are available only when recorded in Notes. Invoice attachments were not individually checked. Unclassified records require review.